

NETWORK 1 - MAIN SCHOOL - BLOCK 1* Indicates action required

No.	BLOCK No. & REF.	ROOM REF.	ROOM DESCRIPTION	EQUIPMENT REF.	EQUIPMENT ID REF.	ZONE	EQUIPMENT DESCRIPTION	INSTALLED	REPLACED	REPOSITIONED	BATTERIES REPLACED	ORDER NO./CONTRACTOR	REMARKS
74	1-Main School	0/121	HS/ICT7/Nursery/ Corridor	M/074	7E521	22	Call Point	2003			08/03/2017	Hentland changed batteries	Adjacent Isolation room
75	1-Main School	0/119A	Nursery Entrance Lobby	M/075	78760	22	Call Point	2003			27/07/2017	Site Team changed batteries	
76	1-Main School	0/119	Nursery Playroom off entrance lobby	M/076	163FA	22	Siren/Sounder and Beacon	2003					
77	1-Main School	0/127	Junior Kitchen	M/077	ADAAB	22	Call Point	2003	27/06/2014		27/06/2014	AD018667-Electrical Services	Final Exit door
78	1-Main School	0/127	Junior Kitchen	M/078	31838	22	Heat Detector	2003			22/12/2016	Site Team changed batteries	Tin foil fitted to battery contacts
79	1-Main School	0/128	Junior Dining Room	M/079	162DE	22	Siren/Sounder	2003			22/12/2016	Site Team changed batteries	Tin foil fitted to battery contacts
80	1-Main School	0/128	Junior Dining Room	M/080	31A9E	22	Call Point	2003			24/10/2017	Site Team changed batteries	Tin foil fitted to battery contacts
81	1-Main School	0/042	Round-about circulation area	M/081	9F625	23	Smoke Detector/Sounder	2003	27/10/2010		20/09/2013	Hentland changed batteries	Smoke detector replaced with smoke detector/sounder
82	1-Main School	0/042	Round-about circulation area	M/082	31AB5	23	Call Point	2003			19/02/2015	Hentland changed batteries	Adjacent final exit double doors.
83	1-Main School	0/068	DT2 - Food Tech. Classroom	M/083	16361	23	Siren/Sounder	2003			06/10/2016	Site Team changed batteries	
84	1-Main School	0/043	M11 - Classroom	M/084	31AB2	23	Call Point	2003		03/08/2015			Adjacent final exit doors
85	1-Main School	0/043	M11 - Classroom	M/085	162E4	23	Siren/Sounder	2003			22/12/2016	Site Team changed batteries	
86	1-Main School	0/049	DT5 - Classroom -External	M/086	82D34	23	Siren/Sounder & Beacon-Ext	2003	14/02/2017		14/02/2017	AD 021109-Electrical Services	Replaced due to window renewal & beacon added
87	1-Main School	0/049	DT5 - Classroom	M/087	B10F2	23	Call Point	2003	27/05/2015			AD019506-Electrical Services	Adjacent final exit doors-Repositioned with door renewal contract
88	1-Main School	External	External to Hall	M/088	7268D	14	Siren/Sounder & Beacon-Ext	2003	20/09/2017		20/09/2017	AD021074-Hentland	Replaced with secondhand device supplied by school
89	1-Main School	0/050	DT5 - Electrical Intake Cupboard	M/089	826C7	23	Smoke Detector	2003					
90	1-Main School	0/045	DT4 - Classroom	M/090	B2401	23	Heat Detector	2003	16/08/2017		16/08/2017	AD021527-Electrical Services	Existing heat detector re-programmed
91	1-Main School	0/045	DT4 - Classroom	M/091	B383D	23	Call Point	2003	16/08/2017		16/08/2017	AD021527-Electrical Services	Replaced by Electrical Services
92	1-Main School	0/051	DT7 - Classroom	M/092	31796	23	Smoke Detector	2003					Cleared by Site Team 07/07/2017
93	1-Main School	0/054	DT6 - Classroom	M/093	16275	23	Siren/Sounder	2003					
94	1-Main School	0/054	DT6 - Classroom	M/094	31ABB	23	Call Point	2003			06/10/2016	Site Team changed batteries	Tin foil fitted to battery contacts
95	1-Main School	0/061	A2 - Classroom	M/095	634F5	24	Smoke Detector/Sounder	2003					
96	1-Main School	0/056	Art Entrance Lobby /Circulation	M/096	72D7A	24	Smoke Detector/Sounder	2003	25/10/2016		25/10/2016	AD020797-Electrical Services	
97	1-Main School	0/056	Art Entrance Lobby /Circulation	M/097	787AE	24	Call Point	2003			04/04/2017	Site Team changed batteries	Adjacent final exit double doors.
98	1-Main School	0/061	A2 - Classroom	M/098	31A99	24	Call Point	2003			26/08/2016	Hentland changed batteries	Adjacent final exit door. - Battery change with Bi annual Test
99	1-Main School		No Device to this reference		No Device		No Device to this reference						
100	1-Main School	0/064	Art Classroom/ Ex Kiln room	M/100	B3844	24	Call Point	2003	16/08/2017		16/08/2017	AD021527-Electrical Services	Replaced by Electrical Services
101	1-Main School	0/067	A3 - Classroom	M/101	B392C	24	Call Point	2003	16/08/2017		16/08/2017	AD021527-Electrical Services	Replaced by Electrical Services
102	1-Main School	0/042	S2 corridor/ round-about/circulation	M/102	AF62A	23	Smoke Detector/Sounder	06/01/2014			22/12/2016	AD 0611 M-Electrical Services	Device reference originally used for A2 Classroom - Cleared 07/07/2017
103	1-Main School	0/071	DT3 Entrance Lobby	M/103	31A83	25	Call Point	2003					Adjacent final exit door.
104	1-Main School	0/069	DT3 - Classroom	M/104	46CB5	25	Smoke Detector/Sounder	2003					Batteries checked 8/04/2015, cleaned & re-fitted
105	1-Main School	0/076	S2 - Lab Classroom	M/105	31AA3	26	Call Point	2003			02/09/2016	Site Team changed batteries	Tin foil fitted to battery contacts
106	1-3 Storey Block	1/016	West Stairwell- First Floor Landing	M/106	31A8C	27	Call Point	2003					
107	1-3 Storey Block	1/016	West Stairwell- First Floor Landing	M/107	3169B	27	Smoke Detector/Sounder	2003					
108	1-3 Storey Block	1/010	First Floor corridor - Adjacent M2	M/108	B2903	27	Smoke Detector	2003	17/08/2016		17/08/2016	AD020625-Electrical Services	
109	1-3 Storey Block	1/010	First Floor corridor - Adjacent Maths Store	M/109	31643	27	Smoke Detector/Sounder	2003			13/10/2016	Site Team changed batteries	
110	1-3 Storey Block	1/010	First Floor corridor - Adjacent M4	M/110	3164D	27	Smoke Detector/Sounder	2003			13/10/2016	Site Team changed batteries	
111	1-3 Storey Block	1/011	East Stairwell- First Floor Landing	M/111	31675	27	Smoke Detector/Sounder	2003			13/10/2016	Site Team changed batteries	
112	1-3 Storey Block	1/012	East Stairwell- First Floor Landing	M/112	31AA2	27	Call Point	2003					
113	1-3 Storey Block	2/001	West Stairwell- Second Floor Landing	M/113	B383F	28	Call Point	2003	16/08/2017		16/08/2017	AD021527-Electrical Services	Replaced by Electrical Services
114	1-3 Storey Block	2/001	West Stairwell- Second Floor Landing	M/114	80909	28	Smoke Detector/Sounder	2003	18/01/2012		15/03/2011	Hentland changed batteries	
115	1-3 Storey Block	2/016	Second Floor Corridor	M/115	58DBA	28	Smoke Detector	2003					Adjacent M9/KS3Leaders Office
116	1-3 Storey Block	2/016	Second Floor Corridor	M/116	AB236	28	Smoke Detector/Sounder	2003			27/09/2012	AD00244 M - Hentland	Adjacent L1
117	1-Main School		No Device to this reference		No Device		No Device to this reference		13/10/2017			AD021074-Hentland	Reprogrammed as M/088 on panel
118	1-3 Storey Block	2/016	Second Floor Corridor	M/118	4470B	28	Smoke Detector/Sounder	2003	18/02/2016		18/02/2016	AD020237-Electrical Services	Adjacent L3/East Stairwell- Works arising from FRA
119	1-3 Storey Block	2/017	East Stairwell- Second Floor Landing	M/119	32CFC	28	Call Point	2003					
120	1-3 Storey Block	2/017	East Stairwell- Second Floor Landing	M/120	442AB	28	Smoke Detector/Sounder	2003					
121	1-3 Storey Block	0/019	West Stairwell- Ground Floor Landing/ Final Exit	M/121	B2905	20	Smoke Detector	2003	25/08/2016		25/08/2016	AD020625-Electrical Services	
122	1-3 Storey Block	0/019	West Stairwell- Ground Floor Landing/ Final Exit	M/122	31A72	20	Call Point	2003			06/10/2016	Site Team changed batteries	Adjacent final exit double doors - Tin foil fitted to battery contacts.
123	1-3 Storey Block	2/017	East Stairwell- Second Floor Landing	M/123	48133	30	Smoke Detector/Sounder	2003			12/10/2009	Waldron changed batteries	Adjacent Lift
124	1-Main School	0/051	DT7 - Classroom	M/124	9F01B	23	Siren/Sounder	2003		27/10/2010			Originally default device placed in DT7
125	1-Main School	0/084	Science Corridor o/s store room adjacent S11 & ICT6	M/125	71702	20	I/O unit to auto fire doors	2003			13/10/2017	AD021641-Hentland changed batt's	I/O Unit
126	1-Main School	0/092	Female Staff Toilet - Music	M/126	F0F0D	21	Transponder	2003					
127	1-3 Storey Block	0/038	East Stairwell - Ground Floor Entrance	M/127	3C107	18	Call Point	2003					Adjacent final exit double doors by lift.
128	4 - PE,DT, Grounds	0/001	P.E. Base/Office	M/128	3D929	20	Call Point	2003					Adjacent final Exit door
129	1-Main School	0/054	DT6 - Classroom	M/129	F0F0E	23	Transponder	2003					
130	1-Main School	0/150	S8 - Lab Classroom	M/130	3670A	19	Heat Detector	2003			22/12/2016	Site Team changed batteries	
131	1-Main School	0/150	S8 - Lab Classroom	M/131	378F2	19	Heat Detector	2003			08/04/2015	Site Team changed batteries	
132	1-Main School	0/150	S8 - Lab Classroom	M/132	37731	19	Call Point	2003					Adjacent East final exit door
133	1-Main School	0/151	S7 - Lab Classroom	M/133	37864	19	Heat Detector	2003			08/04/2015	Site Team changed batteries	
134	1-Main School	0/151	S7 - Lab Classroom	M/134	378F9	19	Heat Detector	2003					
135	1-Main School	0/151	S7 - Lab Classroom	M/135	37797	19	Call Point	2003			19/02/2015	AD019263 - Hentland batteries	Battery change with Bi annual Test
136	1-3 Storey Block	External	Front entrance	M/136	B300A	18	Siren/Sounder	2003	07/03/2017		07/03/2017	AD21074 - Hentland	New siren installed by Hentland
137	1-Main School	0/150	S8 - Lab Classroom	M/137	B2D0E	19	Call Point	2003	14/02/2017		14/02/2017	AD 021109-Electrical Services	Adjacent South final exit door
138	1-Main School	0/051	DT7 - Classroom	M/138	72797	24	Call Point	2003					Adjacent final exit door
139	1-Main School	0/058	A1 - Classroom	M/139	7341F	24	Siren/Sounder	2003			26/08/2016	Hentland changed batteries	Battery change with Bi annual Test
140	1-Main School	0/061	A2 - Classroom	M/140	73422	24	Siren/Sounder	2003			26/08/2016	Hentland changed batteries	Battery change with Bi annual Test
141	1-Main School	0/067	A3 - Classroom	M/141	72E3D	24	Siren/Sounder	2003			26/08/2016	Hentland changed batteries	Battery change with Bi annual Test
142	1-Main School	0/053B	A1 - Classroom Store	M/142	7D9EC	24	Smoke Detector	2003	27/05/2015		26/08/2016	AD19449 - Electrical Services	Repositioned from Nursery/ICT7 Corridor
143	1-Main School	0/058	A1 - Classroom	M/143	5FD36	24	Smoke Detector	2003					
144	1-Main School	0/015A	Server room off stage	M/144	7E8D0	16	Smoke Detector	19/01/2012				AD016408 - Waldon Security	Work organised by Cornwall Council
145	1-Main School	0/109	HS- Classroom	M/145	AFF80	22	Smoke Detector	2003		17/08/2016		AD020604 - Electrical Services	Repositioned from History Corridor
146	1-3 Storey Block	2/016A	Photo copier area off second floor corridor	M/146	804D9	28	Smoke Detector	20/08/2014				AD018834 - Electrical Services	Installed with IT store works
147	1-Main School	0/015B	Exams Store off stage	M/147	3185A	16	Smoke Detector	20/08/2014		20/08/2014	05/04/2017	AD018834 - Electrical Services	Repositioned from ICT1 - Batteries changed by site Team
148	1-Main School	0/064	Art Classroom/ Ex Kiln room	M/148	80D66	24	Smoke Detector/Sounder	2003		25/08/2016	04/04/2017	AD020590 - Electrical Services	Repositioned from Dark room with refurb - Batteries changed by Site Team

NETWORK 1 - MAIN SCHOOL - BLOCK 1-* Indicates action required

No.	BLOCK No. & REF.	ROOM REF.	ROOM DESCRIPTION	EQUIPMENT REF.	EQUIPMENT ID REF.	ZONE	EQUIPMENT DESCRIPTION	INSTALLED	REPLACED	REPOSITIONED	BATTERIES REPLACED	ORDER NO./CONTRACTOR	REMARKS
*149	1-Main School	0/086	S10 - Lab Classroom	M/149	A93D5	20	Smoke Detector/Sounder	03/08/2015	17/08/2017		17/08/2017	AD021074-Hentland	*Not sounding - Replacement to be installed by Hentland.
150	1-Main School	0/110	Isolation Room	M/150	B17A3	22	Smoke Detector/Sounder	25/08/2015				AD019698 - Ron Bullock	Installed by Electrical Services as sub contractor with refurb. Works
151	1-Main School	0/067	A3 - Classroom	M/151	B28A7	24	Smoke Detector	17/08/2016			17/08/2016	AD020590 - Electrical Services	Installed with dark room refurb works
152	1-Main School	0/141	DR1 - Drama Classroom	M/152	B1EAD	19	Call Point	18/02/2016				AD020237 - Electrical Services	Installed following FRA
153	1-Main School	0/109	HS- Classroom	M/153	B1F57	24	Call Point	18/02/2016				AD020237 - Electrical Services	Installed following FRA
154	1-3 Storey Block	0/031A	Ground Floor Corridor	M/154	B2004	18	Smoke Detector/Sounder	18/02/2016				AD020237 - Electrical Services	Adjacent Library-Installed following FRA
155	1-3 Storey Block	1/010	First Floor Corridor	M/155	B1FF7	27	Smoke Detector/Sounder	18/02/2016				AD020237 - Electrical Services	Adjacent M6/M7-Installed following FRA
156	1-3 Storey Block	2/016	Second Floor Corridor	M/156	B2000	28	Smoke Detector/Sounder	18/02/2016				AD020237 - Electrical Services	Adjacent Girls toilets-Installed following FRA
157	1-Main School	0/035	ICT 4	M/157	B28DE	18	Smoke Detector/Sounder	2003			14/02/2017	-Electrical Services 14/02/2017	Re-configured on panel due to duplication with Gym S/D
158	1-Main School	0/042	Roundabout	M/158	143B6	20	Siren/Sounder	17/08/2017			23/10/2017	AD021527-Electrical Services	Secondhand replacement equipment supplied by school - Sounding Correctly after last service
159	1-Main School	0/038	East Stairwell Ground Floor Entrance /outside lift	M/159	30A02	18	Smoke Detector/Sounder	2003			23/10/2017	-Electrical Services 14/02/2017	Re-configured on panel due to duplication with Gym S/D
160	1-Main School	0/084	Science Corridor/ Circulation/ Adjacent S3 & S4	M/160	744B6	20	Siren/Sounder	17/08/2017			17/08/2017	AD021527-Electrical Services	Secondhand replacement equipment supplied by school
161	1-Main School	0/106	BS1 - Classroom	M/161	A4466	20	Smoke Detector/Sounder	17/08/2017			17/08/2017	AD021528 - Electrical Services	Secondhand replacement equipment supplied by school
162	1-Main School	0/121	HS & Business Corridor/Adjacent HS2 & BS1	M/162	B384F	20	Call Point	18/08/2017			18/08/2017	AD021528 - Electrical Services	New equipment installed due to additional fire exit door
*163	1-Main School	0/049	DT5 - Classroom	M/088 ?	?	?	Siren/Sounder	?					*Not included on panel or text file but working -marked M/088- *Include

NETWORK 2 - SIXTH FORM BLOCK 2-* Indicates action required

No.	BLOCK No. & REF.	ROOM REF.	ROOM DESCRIPTION	EQUIPMENT REF.	EQUIPMENT ID REF.	ZONE	EQUIPMENT DESCRIPTION	INSTALLED	REPLACED	REPOSITIONED	BATTERIES REPLACED	ORDER NO./CONTRACTOR	REMARKS
1	2-Sixth Form	N/A	N/A	2/001	00001	5	Hardwired Call Point	2003					Default Device 001- Spare on panel
2	2-Sixth Form	N/A	N/A	2/002	00002	1	Hardwired Sounder 1	2003					Default Device 002- Spare on panel
3	2-Sixth Form	N/A	N/A	2/003	00003	1	Hardwired Sounder 2	2003					Default Device 003- Spare on panel
4	2-Sixth Form	N/A	N/A	2/004	00004	3	Monitored 24 volt Output	2003					Default Device 004- Spare on panel
5	2-Sixth Form	1/023	G4 - Classroom	2/005	31857	3	Smoke Detector	2003					Extra Classroom Formed September 2014 from ICT1
6	2-Sixth Form	1/022	ICT1 - Classroom	2/006	B0505	1	Smoke Detector/Sounder	2003	20/08/2014			AD018833- Electrical Services	Smoke detector replaced with smoke detector/sounder
7	2-Sixth Form	1/001	East Stairwell - First Floor Landing	2/007	B0311	3	Smoke Detector	2003					Outside ICT1 - Tin Foil fitted to contacts
8	2-Sixth Form	1/001	East Stairwell - First Floor Landing	2/008	31A6E	3	Call Point	2003			24/10/2017	Site Team changed batteries	Adjacent E1/E2
9	2-Sixth Form	1/001A	First Floor corridor by lift	2/009	63536	3	Smoke Detector/Sounder	2003					Batteries changed Electrical Services-AD021772 -Jackson Lifts drop lift cab
10	2-Sixth Form	Lift	Lift Shaft	2/010	7341F	3	Smoke Detector	2003	08/04/2016		03/11/2017	AD020305 - Electrical Services	Adjacent E3 - Tin foil fitted to contacts
11	2-Sixth Form	1/001A	First Floor corridor by lift	2/011	31A84	2	Call Point	2003			24/10/2017	Site Team changed batteries	Adjacent E4
12	2-Sixth Form	1/001A	First Floor corridor by lift	2/012	7234A	3	Smoke Detector/Sounder	2003					Store off first floor corridor by lift
13	2-Sixth Form	1/007	First Floor English Store	2/013	31858	3	Smoke Detector	2003					Staircase off main entrance
14	2-Sixth Form	1/015	West Stairwell - First Floor Landing	2/014	B2B84	3	Smoke Detector	2003	25/10/2016		25/10/2016	AD020797 - Electrical Services	Staircase off main entrance - Battery change with Bi annual Test
15	2-Sixth Form	1/015	West Stairwell - First Floor Landing	2/015	A67EE	3	Call Point	2003					Adjacent E8
16	2-Sixth Form	1/021	First Floor corridor	2/016	31A73	3	Call Point	2003					Adjacent E5
17	2-Sixth Form	1/021	First Floor corridor	2/017	99432	3	Smoke Detector/Sounder	2003	08/06/2010		08/03/2017	Hentland changed batteries	
18	2-Sixth Form	1/011	E7 - Classroom	2/018	5F302	3	Smoke Detector	2003					Adjacent final exit door -Tin foil fitted to battery contacts
19	2-Sixth Form	0/035	EPR1 - Classroom	2/019	316F4	1	Call Point	2003			26/08/2016	Hentland changed batteries	Adjacent EPR1/H1- Second hand equipment supplied by school
20	2-Sixth Form	0/0117A	Ground Floor lobby	2/020	A43E1	1	Smoke Detector	2003	17/08/2017		17/08/2017	AD021527 -Electrical Services	Adjacent final exit door -Tin foil fitted to battery contacts
21	2-Sixth Form	0/033	H1 - Classroom	2/021	31A6C	1	Call Point	2003			26/08/2016	Hentland changed batteries	Adjacent final exit door
22	2-Sixth Form	0/012	E9 - Classroom	2/022	31A7F	1	Call Point	2003					Adjacent final exit door
23	2-Sixth Form	0/016	E10 - Classroom	2/023	31A7A	1	Call Point	2003					Adjacent final exit door
24	2-Sixth Form	0/0117	Ground Floor corridor	2/024	31A87	1	Call Point	2003					Adjacent double doors to glazed link
25	2-Sixth Form	0/0117	Ground Floor corridor	2/025	B2B81	1	Smoke Detector	2003	25/10/2016		25/10/2016	AD020797 - Electrical Services	Bottom of East Stairs * Replaced with Secondhand device 17/11/17 Elec. Serv. To return devices
26	2-Sixth Form	0/026	Ground Floor corridor	2/026	5FF13	1	Smoke Detector	2003					Adjacent E9/E10
27	2-Sixth Form	0/003	Ground Floor corridor	2/027	6365D	1	Smoke Detector/Sounder	2003			04/10/2016		Adjacent Disabled Toilet-Tin foil fitted to battery contacts
28	2-Sixth Form	0/003	Ground Floor corridor	2/028	31A65	1	Smoke Detector	2003		07/03/2017		AD021074 - Hentland	Adjacent Cir'lum Supp't Resource-2/033 Repositioned by Hentland
29	2-Sixth Form	0/002	Ground Floor corridor	2/029	B167B	1	Smoke Detector/Sounder	2003	07/03/2017			AD021074 - Hentland	Main entrance corridor bottom of West stairwell
30	2-Sixth Form	0/002	Ground Floor corridor	2/030	32CC1	1	Call Point	2003					Adjacent final exit double doors
31	2-Sixth Form	0/003	Ground Floor corridor	2/031	71E02	1	Smoke Detector	2003					Adjacent Girls toilets/Ass't Heads Office
32	2-Sixth Form	0/004	Ground Floor corridor	2/032	95F59	1	Smoke Detector/Sounder	2003	21/12/2016		21/12/2016	AD021069 - Electrical Services	Replaced with Second hand equipment supplied by school
33	2-Sixth Form	0/004	Ground Floor corridor	2/033	B312A	1	Smoke Detector/Sounder	2003	07/03/2017			AD021074 - Hentland	Adjacent ICT3/Silent Study Room
34	2-Sixth Form	0/004	Ground Floor corridor/link outside Support Office	2/034	585BC	1	Call Point	2003			28/07/2017	Site Team cleaned 24/10/2017	Adjacent final exit door - Clean a with Tin foil fitted to battery contacts
35	2-Sixth Form	0/031	ICT3 - Classroom	2/035	31A71	1	Call Point	2003					Adjacent final exit door
36	2-Sixth Form	0/024	Silent Study Room	2/036	31A93	1	Call Point	2003					Adjacent final exit door
37	2-Sixth Form	0/018A	Electrical Intake cupboard	2/037	A439F	1	Smoke Detector	2003			28/07/2017	Site Team changed batteries	Tin foil fitted to battery contacts by Hentland March 2017 - Fault
38	2-Sixth Form	0/013	Boiler Room	2/038	316A0	1	Heat Detector/Sounder	2003			05/04/2017	Site Team changed batteries	
39	2-Sixth Form	0/013	Boiler Room	2/039	787B7	1	Call Point	2003			28/07/2017	Site Team changed batteries	Adjacent final exit double doors
40	2-Sixth Form	0/011	Lift Motor Room	2/040	317A9	1	Heat Detector	2003			28/07/2017	Site Team changed batteries	
41	2-Sixth Form	0/028	Common Room	2/041	318AE	2	Call Point	2003			17/02/2017	Hentland changed batteries	Site Team cleaned contacts & refitted batteries 24/10/2017
42	2-Sixth Form	0/028	Common Room	2/042	72D7A	3	Call Point	2003			25/10/2016	Electrical Services changed batteries	Adjacent final exit double doors by kitchenette
43	2-Sixth Form	0/028	Common Room	2/043	31A90	2	Call Point	2003			05/04/2017	Site Team changed batteries	Adjacent final exit double doors - Foil fitted to contacts
44	2-Sixth Form	0/028	Common Room	2/044	71DDA	2	Smoke Detector	2003					Adjacent internal entrance double doors
45	2-Sixth Form	0/028	Common Room	2/045	793DB	2	Smoke Detector/Sounder	2003					
46	2-Sixth Form	0/026	Head of sixth form Office	2/046	F0F0C	2	Transponder	2003					
47	2-Sixth Form	No Ref	Spare - No Device Location	No ref.	No ID Ref.	None	No Device						No device location and reference on fire panel
48	2-Sixth Form	No Ref	Spare - No Device Location	No ref.	No ID Ref.	None	No Device						No device location and reference on fire panel
49	2-Sixth Form	0/017A	Ground Floor lobby	2/049	46DCC	1	Siren/Sounder	2003			04/03/2015		
50	2-Sixth Form	N/A	Default Device - Hardwired electro magnetic closers	2/0128	65E4A	1	Door Closers to corridors	2003			13/10/2017	AD021641 - Hentland	Hardwired electromagnetic door release hold backs to corridor fire doors
51	2-Sixth Form	0/018A	Electrical Intake cupboard	No Ref.	No ID Ref.	None	Slave Fire Panel Network 2	2003		06/07/2017		AD021480 - Cashel Fire Ltd.	Secondhand Replacement Panel
*52	2-Sixth Form	1/023	G4 - Classroom	2/007 ?	B0311?	3?	Siren/Sounder-*Not marked	2003	06/10/2014		06/10/2014	AD019026 - Electrical Services	Extra Classroom Formed September 2014 - Not included on panel -*Include

NETWORK 3 - SIXTH FORM - BLOCK 10 - * Indicates action required

No.	BLOCK No. & REF.	ROOM REF.	ROOM DESCRIPTION	EQUIPMENT REF.	EQUIPMENT ID REF.	ZONE	EQUIPMENT DESCRIPTION	INSTALLED	REPLACED	REPOSITIONED	BATTERIES REPLACED	ORDER NO./CONTRACTOR	REMARKS
1	10-Sixth Form	N/A	N/A	3/001	00001	1	Hardwired Call Point	2003					Default Device 001- Spare on panel
2	10-Sixth Form	N/A	N/A	3/002	00002	1	Hardwired Sounder 1	2003					Default Device 002- Spare on panel
3	10-Sixth Form	N/A	N/A	3/003	00003	1	Hardwired Sounder 2	2003					Default Device 003- Spare on panel
4	10-Sixth Form	N/A	N/A	3/004	00004	1	Monitored 24 volt Output	2003					Default Device 004- Spare on panel
5	10-Sixth Form	0/019	Boiler Room	3/005	3B275	1	Call Point	2003			28/07/2017	Site Team changed batteries	Adjacent entrance door
6	10-Sixth Form	0/013	H2 - Classroom	3/006	3B290	2	Call Point	2003			18/02/2015	Site Team changed batteries	Adjacent final exit door
7	10-Sixth Form	1/003	North Stair - First Floor Landing	3/007	3B150	4	Call Point	2003					Adjacent disabled WC/ICT9
8	10-Sixth Form	1/018	First Floor Glazed link Corridor	3/008	3B18A	5	Call Point	2003					Link corridor to Block 2
9	10-Sixth Form	0/020	Ground Floor link Corridor	3/009	3B1DC	1	Call Point	2003			18/02/2015	Site Team changed batteries	Adjacent west final double exit doors link corridor to Block 2
10	10-Sixth Form	0/009	EPR3 - Classroom	3/010	3B2A1	2	Call Point	2003			16/01/2013	AD0342 M Hentland	Adjacent final exit door
11	10-Sixth Form	0/006	H3 - Classroom	3/011	3B1C5	2	Call Point	2003					Adjacent final exit door
12	10-Sixth Form	0/004	Entrance Lobby	3/012	3B157	4	Call Point	2003					Adjacent final exit double doors
13	10-Sixth Form	0/012	EPR2 - Classroom	3/013	3B14E	2	Call Point	2003			08/04/2015	Site Team changed batteries	Adjacent final exit door
14	10-Sixth Form	0/020	Ground Floor link Corridor	3/014	3B790	1	Call Point	2003			18/02/2015	Site Team changed batteries	Adjacent east final double exit doors link corridor to Block 2
15	10-Sixth Form	1/006	G2 - Store	3/015	3BD46	6	Smoke Detector	2003			06/10/2014		Classroom store
16	10-Sixth Form	0/020	Ground Floor link Corridor	3/016	A43D3	1	Smoke Detector	2003					Adjacent west final double exit doors link corridor to Block 2
17	10-Sixth Form	0/014	H2 - Store	3/017	3BD37	2	Smoke Detector	2003			29/05/2014		Classroom store
18	10-Sixth Form	1/013	First Floor Corridor	3/018	B2401	3	Smoke Detector	2003	16/08/2017		25/10/2017	AD021527 - Electrical Services	Adjacent Classrooms G3/ICT2-Secondhand equipment supplied by school
19	10-Sixth Form	0/011	EPR2 - Store	3/019	3BB39	2	Smoke Detector	2003			12/10/2016		Classroom store - Tin foil fitted to battery contacts
*20	10-Sixth Form	0/007	H3 - Store	3/020	8D16F	2	Smoke Detector	2003	14/08/2009				Classroom store - Not included on panel or text file - *Include
*21	10-Sixth Form	0/015	Ground Floor Corridor	3/021	76B1E	2	Smoke Detector	2003					Adjacent Classrooms EPR2/H2 - *Change description on panel
*22	10-Sixth Form	1/013	First Floor Corridor - Adjacent Classrooms G1 and G2	3/022	3BD36	6	Smoke Detector	2003			28/07/2017	Site Team changed batteries	* Isolated due to false alarm on 31-10-2017
23	10-Sixth Form	0/008	H3 - Electrical Intake Cupboard	3/023	3BD48	2	Smoke Detector	2003					Classroom store/ intake cupboard
24	10-Sixth Form	1/010	G3 - Store	3/024	3BD4F	6	Smoke Detector	2003					Classroom store- Batteries checked & refitted 08/04/2015
25	10-Sixth Form	1/012	ICT2 - Store	3/025	3BD45	6	Smoke Detector	2003					Classroom store
26	10-Sixth Form	1/008	G1 - Store	3/026	A439E	3	Smoke Detector	2003			25/10/2017	Site Team changed batteries	Classroom store
27	10-Sixth Form	0/010	EPR3 - Store	3/027	3BD3F	2	Smoke Detector	2003			26/08/2016	Hentland changed batteries	Classroom store- Tin foil fitted to battery contacts
*28	10-Sixth Form	0/005	Ground Floor Corridor	3/028	7FE23	3	Smoke Detector	2003	14/08/2009			Electrical Services	Adj. IT Support/Finance Office- Not included on panel or text file - *Include
29	10-Sixth Form	0/019	Boiler Room - BMS	3/029	474BB	1	Heat Detector/Sounder	2003					
30	10-Sixth Form	1/004	G2 - Classroom	3/030	7E6AE	6	Smoke Detector/Sounder	2003			28/07/2017	Site Team changed batteries	
31	10-Sixth Form	1/009	G3 - Classroom	3/031	47781	6	Smoke Detector/Sounder	2003					
32	10-Sixth Form	1/003	North Stair - First Floor Landing	3/032	47748	4	Smoke Detector/Sounder	2003					Adjacent disabled WC/ICT9
33	10-Sixth Form	0/015	Ground Floor Corridor	3/033	47770	4	Smoke Detector/Sounder	2013					Adjacent Classrooms EPR3/H3
34	10-Sixth Form	1/018	First Floor Glazed link Corridor	3/034	A690D	1	Smoke Detector/Sounder	2003			28/07/2017	Site Team changed batteries	Site Team Cleaned terminals- 24/10/2017 & re-fitted batteries
35	10-Sixth Form	0/013	H2 - Classroom	3/035	47793	2	Smoke Detector/Sounder	2003					
36	10-Sixth Form	0/020	Ground Floor link Corridor	3/036	4776E	1	Smoke Detector/Sounder	2003					Adjacent Boys and Girls Toilets
37	10-Sixth Form	1/001	ICT9 - Classroom	3/037	4774F	4	Smoke Detector/Sounder	2003					
38	10-Sixth Form	0/012	EPR2 - Classroom	3/038	4777B	2	Smoke Detector/Sounder	2003					
39	10-Sixth Form	0/006	H3 - Classroom	3/039	7E6B3	2	Smoke Detector/Sounder	2003			28/07/2017	Site Team changed batteries	
40	10-Sixth Form	1/018	First Floor Glazed link Corridor	3/040	4777F	5	Smoke Detector/Sounder	2003					Adjacent Boys and Girls Toilets
41	10-Sixth Form	0/009	EPR3 - Classroom	3/041	47791	2	Smoke Detector/Sounder	2003			26/08/2016	Hentland changed batteries	Tin foil fitted to battery contacts
42	10-Sixth Form	0/004	Entrance Lobby	3/042	47780	4	Smoke Detector/Sounder	2003	27/08/2014			Electrical Services	Replacement from Smoke detector
43	10-Sixth Form	1/005	G1 - Classroom	3/043	4774D	6	Smoke Detector/Sounder	2003					
44	10-Sixth Form	0/003	IT Support	3/044	47796	3	Smoke Detector/Sounder	2003	16/09/2014			Hentland	
45	10-Sixth Form	0/002	Finance Office	3/045	47747	3	Smoke Detector/Sounder	2003					
46	10-Sixth Form	0/001	ICT8 - Classroom	3/046	47753	3	Smoke Detector/Sounder	2003					
47	10-Sixth Form	1/011	ICT2 - Classroom	3/047	47748	1	Smoke Detector/Sounder	2003					
48	10-Sixth Form	1/014	First Floor Girls Toilets	3/048	42AB6	5	Siren/Sounder	2003	28/02/2014		28/02/2014	AD 0651 M - Hentland	
49	10-Sixth Form	0/016	Ground Floor Girls Toilets	3/049	4779A	1	Siren/Sounder	2003					
50	10-Sixth Form	1/017	First Floor Boys Toilets	3/050	475C6	1	Siren/Sounder	2003					
51	10-Sixth Form	0/018	Ground Floor Boys Toilets	3/051	47149	1	Siren/Sounder	2003					
52	10-Sixth Form	0/019	Boiler Room - BMS Shutdown	3/052	451BA	1	I/0052 BMS Shutdown / Sounder	2003					
53	10-Sixth Form	No Ref:	Roof Void above water tanks	3/053	48131	7	Smoke Detector/Sounder	2003	17/04/2014		17/04/2014	AD0682 M - Hentland	I/O Unit located in Boiler Room
54	10-Sixth Form	No Ref:	Roof Void	3/054	4811E	7	Smoke Detector/Sounder	2003			06/10/2014		
*54	10-Sixth Form	*?	Boiler Room	*?	No ID Ref.	*?	Transponder	2003			19/02/2015	Hentland changed batteries	Batteries changed to output module-No reference on panel.
*55	10-Sixth Form	0/008	H3 - Electrical Intake Cupboard	*?	No ID Ref.	*?	Slave Fire Panel Network 3	2003					No reference on panel